

River Fly- In Condominium

Unit: 0312

Owner:

Contact:

Email:

Phone. Fax:

Policy

Type:

OCIP

Number:

Project information

Client information

Carrier Name: TBD but most likely Hudson Excess

river Fly-in Inc.

(954) 941-0900

wasim_us@yahoo.com

Wasim Niazi

Location Site Contact

Street Address: 735 Pilot Lane Name:

County: Title:

City, State - Zip: Merritt Island, FL 32952 Email:

Phone, Fax:

Start Dates

Est. Construction Start: Apr, 30 2021 Trenching of Foundations: Est. Completion:

Vertical Start: Est. Build-out Months: 24

Project Description

Cost Of Construction: 0 Total Units/Homes: 112 Total Buildings: 1

Total Number Of Stories: 0 Below Grade Levels: 0 Avg SqFt Per Unit/Home: 0

Est. Construction Start: Apr, 30 2021 Est. Sqft Below Grade: 0 Avg SqFt Per Building: 0

Current Project Data

Total items reviewed: 1416 Number of open items that are 0 to 15 days old: 0

Total closed items (CDR's): 8 Number of open items that are 16 to 30 days old: 0

Total open items: 0 Number of open items that are 31 to 60 days old: 0

Number of open items that are over 60 days old: 0

Report By: Tyler Sparks

I certify that I have carefully inspected this property on this date. I have no personal interest, present or prospective, in the property, or the onsite personnel. To the best of my knowledge I have reported all noncompliance, work requiring correction, and unacceptable work.

L

Status: Active

01/09/2023

Framing

1.00-Beams and headers are correct size per plans/code.


S - Satisfactory, the system meets plan/code/manufactures specifications

NOTE: Headers are correct size per plan

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:51 AM)








1.01-Post are correct size per plans/code.

S - Satisfactory, the system meets plan/code/manufactures specifications

NOTE: Post are correct size per plan

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:52 AM)







1.03-Hardware is installed per plans, code and manufacturer's specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: Hardware is installed per plan


Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:53 AM)

1.04-Anchor bolts are installed per plans/code.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: Pin shot

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:54 AM)





1.06-Wall framing components have not been over notched or drilled.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: Wall framing is not over notched or drilled

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:54 AM)





1.07-Floor framing components have not been over notched or drilled.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: Floor framing is not over notched or drilled

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:55 AM)







1.15-Stairs are installed per plans/code.

NA - Not Applicable, building type does not contain this system NOTE: Single story unit

Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:55 AM)

2.03-Interior backing has been installed for railing, plumbing and/or electrical items.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: Interior backing is installed per plan specifications Builder Risk Engineer: Tyler Sparks (Feb 5, 2022 10:56 AM)







Rough Trades

1.00-Conductor wiring is installed with proper support and is protected from damage.

S - Satisfactory, the system meets plan/code/manufactures specifications




Tyler Sparks 05-12



1.02-Minimum 1/4 inch of Romex sheathing is in the device box.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 1:58 PM)



1.03-Junction and/or device boxes are not overfilled.

S - Satisfactory, the system meets plan/code/manufactures specifications NOTE: J boxes are not overfilled

Builder Risk Engineer: Tyler Sparks (May 12, 2022 1:58 PM)



1.04-Smoke detectors are in stalled at all required locations.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 1:58 PM)



1.05-Smoke detectors have proper clearances where required.


S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 1:59 PM)






1.06-All outlets and switches are located per plan specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 1:59 PM)







1.07-All low-volt wiring is installed per the plan specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:00 PM)



2.00-Supply lines are installed per the plan and manufacture's specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:00 PM)









2.01-Supply lines are protected from damage.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:01 PM)

2.03-Pex lines have proper clearances where required.


S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:01 PM)






2.04-Sewer lines are installed per plan specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:01 PM)





2.05-Sewer lines are properly slopped to drain.


S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:02 PM)



2.06-Sewer lines are protected from damage.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:02 PM)





2.10-Vents are properly installed and located per plan specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:02 PM)



3.00-Supply and return ducts are installed in a manor to allow for maximum air flow.

S - Satisfactory, the system meets plan/code/manufactures specifications





$3.01 ext{-Supply}$ and return ducts are connected and sealed per code specifications.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:03 PM)





3.04-Exhaust ducts are properly installed and terminate at safe locations.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:03 PM)



3.06-Fireplace is installed per the manufacture's specifications.

NA - Not Applicable, building type does not contain this system Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:03 PM)

Rated Assemblies

1.00-Wall assembly Fire Blocking/Draft Stopping has been installed per code.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:06 PM)



1.01-Floor assembly Fire Blocking/Draft Stopping has been installed per code.

NOTE:



1.02-Stair assembly Fire Blocking/Draft Stopping has been installed per code.

NA - Not Applicable, building type does not contain this system Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:06 PM)

2.04-Two Hour wall assemblies are installed per plan/code requirements.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:06 PM)






2.05-Two Hour floor/ceiling assemblies are installed per plan/code requirements.

S - Satisfactory, the system meets plan/code/manufactures specifications

Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:06 PM)





2.07-Non-rated penetrations are properly addressed per plan/code.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:06 PM)

2.10-Through penetrations are properly addressed per plan/code.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:07 PM)



2.11-Doors within rated assemblies are properly rated.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:07 PM)



3.00-CPVC Fire Suppression system is properly installed to industry standards.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:07 PM)





3.01-CPVC Fire Suppression system is protected from damage.


S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:08 PM)

3.04-Fire suppression sprinkler heads are clean, free of paint and are not obstructed.

S - Satisfactory, the system meets $\ensuremath{\text{plan/code/manufactures}}$ specifications

Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:08 PM)





5.00-Smoke detectors are installed at all required locations.

S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:08 PM)



5.01-Smoke detectors have proper clearances where required.S - Satisfactory, the system meets plan/code/manufactures specifications Builder Risk Engineer: Tyler Sparks (May 12, 2022 2:08 PM)



