

820 Brevard Avenue, Rockledge, FL 32955 - P: 321.638.0808 - F: 321.638.0978

**Construction Materials Testing Services
FIELD AND LABORATORY REPORT COVER PAGE**

Client: Tomp Construction
1996 US Highway 1
Rockledge, FL 32955

Project: River Fly-In Condominium CMT
715 Pilot Lane, Merritt Island, Brevard County, FL


As requested, Universal Engineering Sciences, LLC. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

| Work Order No. | Date | Type of Report |
|----------------|------------|-------------------------|
| 155956-1 | 06/03/2022 | Field Inspection Report |

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned.

Sincerely,
Universal Engineering Sciences, LLC.
FBPE Registry No. 00000549



Richard E. Hoaglin, P.E.
FLORIDA
Professional Engineer No. 48796

This item has been electronically signed and sealed by Richard E. Hoaglin, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UES Project No: 0310.2100154.0000

UES DOCS No:

UES Report No: 03-155956

On-Site Time (hrs): 0.50

Lab Time (hrs): 0.00

Travel Time (hrs): 0.75

Total Time (hrs): 1.25

820 Brevard Avenue, Rockledge, FL 32955 - P: 321.638.0808 - F: 321.638.0978

Inspection Report

Client: Tomp Construction
1996 US Highway 1
Rockledge, FL 32955

Project: River Fly-In Condominium CMT
715 Pilot Lane, Merritt Island, Brevard County, FL

Date of Activity: 06/03/2022

Technician: Cecil Stoughton

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of a steel inspection on Parapet walls.

Plans call for (4) #10 screws at the top and bottom of the kicker studs; inspection revealed that there were only (3) installed.

Re-inspection will be required at a later date.

Ref: CFS308 plan detail.